


PHOTOS



Stone Check Dam installed at outfall



Stone Check Dam installed at outfall

Needham DPW
Rosemary Lake Dredging



Stone Check Dam installed at outfall



Office trailer at Staging Area



Tuesday (11/19/2019)



Friday (11/22/2019)

Station 1 (Petrini Property) – Turbidity and sediment depth readings taken on Tuesday and Friday. Turbidity decreased at Station 1.



Fish near stake past foot bridge. (11/22/2019)



Fish swimming upstream toward Lake. (11/22/2019)

Station 1 (Petrini Property) – Turbidity and sediment depth readings taken on Tuesday and Friday. Fish noted at Station 1 (near outfall and past foot bridge).

Needham DPW
Rosemary Lake Dredging



Tuesday (11/19/2019)



Friday (11/22/2019)

Station 2 (West Street) – Turbidity and sediment depth readings taken on Tuesday and Friday. Turbidity decreased at Station 2.



Station 5.1 and 5.2 (11/22/2019)

Station 5.1 and 5.2 – Edge of Bank shown. Turbidity and sediment depth readings taken on Friday. Rain occurred during monitoring.



Station 5.3(11/22/2019)

Station 5.3 – Edge of Bank shown. Turbidity and sediment depth readings taken on Friday. Rain occurred during monitoring.



Station 5.3 (11/22/2019)

Station 5.3 – Turbidity and sediment depth readings taken on Friday. Rain occurred during monitoring.



Station 5.4 (11/22/2019)

Station 5.4– Edge of Bank shown. Turbidity and sediment depth readings taken on Friday. Rain occurred during monitoring.



Station 5.5 (11/22/2019)

Station 5.5 – Edge of Bank shown. Turbidity and sediment depth readings taken on Friday. Rain occurred during monitoring.