


PHOTOS



Removing existing traffic loops while excavating for a test pit at the northeast corner of Great plain Ave. and Chapel St.
8/7/16



Excavating a test pit at the intersection of Chapel St and Great Plain Ave.
8/7/16

PHOTOS



Typical parking restriction sign posted on parking meter for impending work
8/8/16



Removing existing traffic loops while excavating for test pit at southwest corner of Great Plain Ave. and Dedham Ave.
Also showing plate compactor for trench compaction
8/8/16

PHOTOS



Typical soil (of good quality) being encountered in excavations in various test pit locations
8/7/16



Drainage installation showing removal of existing concrete drain pipe at west end of project
8/10/16