



ENGINEERING SUCCESS TOGETHER

WEEKLY SUMMARY REPORT

Client: Needham DPW
Contract: Rosemary Lake Dredging
Contractor: Maverick Construction Co., Inc.

Dates: 9/16/2019 to 9/20/2019
Inspector(s) on site:

WORK COMPLETED THIS WEEK

- Equipment procurement and project submittal preparation.
- Conducted monitoring along Rosemary Brook and collected outfall water samples along Rosemary Brook for stormwater parameters.

WORK ANTICIPATED FOR NEXT WEEK

- Weekly turbidity monitoring to be conducted along Rosemary Brook.
- Equipment procurement for construction and project submittal preparation. Maverick is currently working on the Sediment Sampling Plan followed by the Material Management and Dewatering plan.

PHOTOS




Station 1 (Petrini Apartments) – Monitoring and water sampling took place at Station 1. (9/16/2019)



Statio 2 (West Street) – Monitoring and water sampling took place at Station 2. (9/16/2019)



**Central Avenue Culvert – Outfall water sample collected at the Central Avenue Culvert.
(9/16/2019)**



**Central Avenue Culvert – Outfall water sample collected at the Central Avenue Culvert.
(9/16/2019)**