

PHOTOS



Staging Area – Signage placed in staging area. A copy of the Superceding Order of Conditions is located on Site. (8/27/2019)



Staging Area – Erosion Controls installed around staging area. (8/27/2019)



Staging Area – tree protection installed. (8/27/2019)



Staging Area – Erosion Controls installed in staging area. (8/27/2019)



Station 1 (Petrini Apartments) – Turbidity Curtain installed. (8/28/2019)



**Station 1 (Petrini Apartments) – Water level approximately 3 inches higher than previous week.
(8/30/2019)**