

PHOTOS



Emergency spill equipment at Staging Area



Dense grade delivery to work pad (1/21/2020)



Work pad progress. Crane mats set up on pad (1/23/2020)



Crane mats placed on work pad



Work pad progress (1/23/2020)



Work pad progress (1/24/2020)



Work pad progress (1/24/2020)



Panorama of work pad progress (1/24/2020) – facing east



Stockpile of material #1 (1/24/2020) – facing east of work pad



Stockpile of material #2 (1/24/2020) – facing south from work pad



Area being dewatered – sump pumps installed and discharging into outfall



Tuesday (1/21/2020)



Thursday (1/23/2020)

Dewatering discharged to Rosemary Lake outfall (1/21/2020)



Paint Filter test inside trailer (1/24/2020)



Backwash treatment tank delivered to Beach parcel