



**Needham DPW  
Rosemary Lake Dredging**



**Concrete benches placed on Site near memorial rock.**



**Guardrails restored around parking lot perimeter**

**Needham DPW  
Rosemary Lake Dredging**



**topsoil and seeding**



**Fencing removed from staging area parking lot**

**Needham DPW  
Rosemary Lake Dredging**



**Rosemary Brook at apartment complex restored**



**Rosemary Lake refilling progress**